



environmental consultants, inc.

www.jbrenv.com

8160 South Highland Drive • Sandy, Utah 84093 [P] 801.943.4144 [F] 801.942.1852

December 23, 2004

Mr. Darron Haddock
Permit Supervisor

Mr. Tom Munson
Senior Reclamation Specialist/Hydrologist

Utah Division of Oil Gas and Mining
1594 West North Temple, Suite 1210
P.O. Box 145801
Salt Lake City, Utah 84114-5801

RECEIVED
DEC 27 2004
DIV. OF OIL, GAS & MINING

RE: Transmittal of Additional Maps; Brush Resources, Inc. MRP Revision

Dear Mr. Haddock and Mr. Munson:

When Mr. Alex Boulton and Mr. John Wagner of Brush Resources, Inc. met with you last week and submitted the revised Mining and Reclamation Plan for the Topaz Mining Properties, two maps were absent from volume II of the two-volume package. These were Plate 3, Soils Map, and Plate 5B, one of the two smaller scale maps showing initial logical mining unit maps at the mine property. Two copies of each of those maps accompany this letter.

Please insert them in the appropriate pockets in each copy of volume II of the revised MRP.

Thank you very much.

Sincerely,

Robert J. Bayer
Managing Principal

Cc: Mr. Alex Boulton, Brush Resources, Inc., w/o attachments
Mr. John Wagner, Brush Resources, Inc., w/ attachments (four copies)